



Figure D-39. Heat sealing a load while tarping.



Figure D-40. Additional spot excavation at ARA-23.





Figure D-41. Preparing an area for excavation.



Figure D-42. Excavating soil northeast of the SL-1 burial ground.





Figure D-43. Turnaround area following excavation.



Figure D-44. Initial excavation of washdown area.





Figure D-45. Dust suppression of washdown area.



Figure D-46. ARA-12 following second lift excavation.





Figure D-47. Aggressive excavation near the SL-1 concrete foundation.



Figure D-48. Additional excavation near the SL-1 concrete foundation.





Figure D-49. Washdown area following initial excavation.



Figure D-50. SL-1 concrete foundation during excavation.